ADDING EDGE BANDING NOTES TO PARTS


- It's the engineer's responsibility to note unique edge banding request.
- Common Edge Banding abbreviations
 - EB Edge Banding
 - o 1 LS One Long Side
 - LS refers to the longest side of part. The number 1 indicates to EB on 1 side. EB operator assumes it the front LS edge.
 - o 2 LS Two Long Sides
 - LS refers to the longest side of part. The number 2 indicates to EB on 2 sides.
 - 1 SS One Short Side
 - SS refers to the short side of part. The number 1 indicates to EB on 1 side.
 - o 2 SS Two Short Side
 - SS refers to the short side of part. The number 2 indicates to EB on 2 sides.
 - All Sides
 - The operator will EB all 4 sides

BEST PRACTICE FOR LABELING

Edge Banding notes should be added during engineering of the product and before processing the WO.

- 1. Open the Part Properties command
- 2. Select the Subassembly, right click to Show Properties
- 3. Find the part
- 4. Add Comment
- 5. Save and Close

If the note was not added before processing, manual notes will need to be added to the nested report.



Work Order: Test

Nesting Optimization Report

12/4/2024 Page 2 of 6


Material Name: #2_.75 PB_1s Plam(UP)_1s Black Liner(down) (49 x 97)

Qty - 1 Sheet # - 5

Batch - B1

Face 5 File - B11009

Face 5 Barcode -



Index#	Part Name	Item#	Cut Rotated Width	Cut Length	Comments
1 Up	per Thick Back	5.00	46	48	Add EB'ing notes here

Part comments show up on the nesting report